

Linked Exterior

Watch this NX Tip Video:



Linked Exterior is a quick way of creating a shell of your assembly by removing interior detail.

We find this is useful when you need to send a supplier the outside shape of your assembly, removing the inner detail & IP.

You need to have an Advanced Assemblies license (available in the Mach 3 bundles).

